Document ID: 4281742 Page 1 of 3

Document ID: 4281742

# #15-05-25-001: Service Stabilitrak Message Displayed, DTC C0196-5A Set in the Electronic Brake Control Module (EBCM) - (Oct 2, 2015)

Subject: Service Stabilitrak Message Displayed, DTC C0196-5A Set in

Electronic Brake Control Module (EBCM)

Models: 2015-2016 Cadillac Escalade Models

2014 Chevrolet Silverado 1500

2015-2016 Chevrolet Silverado, Suburban, Tahoe

2014 GMC Sierra 1500

2015-2016 GMC Sierra, Yukon Models

Attention: This Bulletin also applies to any of the above models that may be

Export vehicles.



Some customers may comment on a Service Stabilitrak message displayed on the Driver Information Center (DIC).

During diagnosis, a technician may find DTC C0196-5A set in the EBCM.

#### Cause

C0196-5A is related to YAW sensor plausibility. Engineering has determined that stone impacts to the underside of the transmission tunnel, right below the SDM, may cause the YAW/Lat sensor located in the SDM to send signal spikes related to the resonant frequencies of the sheet metal; 12-14 kHz range. If the YAW/Lat signals don't line up with vehicle speed and steering angle sensor data, the EBCM will set C0196-5A, plausibility fault. Sometimes the SDM will set C0196-00, invalid yaw rate data fault, if the stone impingement crosses the internal sensor fault threshold while will in turn cause the EBCM to set a C0452-71.

### Correction


If you encounter a vehicle with the above concern, follow diagnostic procedures in SI relative to the DTCs that are present.

After completing necessary repairs to address the DTCs, perform the following procedure. Applying vibration deadening material to the underside of the transmission tunnel is intended to dampen the frequency of stone impacts to prevent a repeat occurrence.

1. Raise and support vehicle. Refer to Lifting and Jacking the Vehicle in SI.



Document ID: 4281742 Page 2 of 3



- 2. Locate area shown above transmission and transfer case, if equipped.
- Ensure the area is free of any debris by cleaning the area with wax and grease remover or equivalent. Ensure area is dry.
- 4. Mark the transmission tunnel as noted.



Wrap and tape off transmission, transfer case, propeller shaft, cables, wiring, exhaust, etc.to protect from overspray as illustrated above.

Note: It is also recommended to protect/tape off the surrounding areas to improve the finished appearance.

Apply vibration deadening/damping material specified to the marked area following manufacturer's guidelines.

Note: It may be necessary to apply the material in 2-3 coats to obtain desired thickness.

Document ID: 4281742 Page 3 of 3



- 7. Inspect the area to ensure coverage of the area is complete and even.
- 8. Remove all material used to protect from overspray.

## Parts Information

| Part Number                                   | Description   | Quantity/Vehicle          | Material<br>Allowance          |
|---|---|---------------------------|--------------------------------|
| 805HD (Obtain<br>from Lord Fusor*)            | High Definition Sealer / Sound<br>Deadener Material [10.5 oz<br>(310.5 mL)] | 1 Application Per<br>Tube | \$25.00 USD<br>(\$30.00 CAD)   |
| Fusor 312 Gun<br>(Obtain from Lord<br>Fusor*) | Sprayable Seam Sealer Tool  | Multiple<br>Applications  | \$204.00 USD<br>(\$237.00 CAD) |

## **Warranty Information**

For vehicles repaired under warranty, use:

| Labor Operation | Description  | Labor Time |
|-----------------|--|------------|
| 1480578*        | Apply Vibration Deadening Material to Transmission<br>Tunnel | 1.0 hr     |

<sup>\*</sup>This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.

