



### Overview

Hardflex® Band Saw Blades are great all-purpose blades for cutting almost any metal. Cuts tough material like stainless steel. Works equally well on solids, tubing and structural shapes.



### Features/Benefits

#### Bi-Metal Construction

Hardflex® blades are built with the best grades of saw steel and the most exacting engineering standards in the industry. The 8% cobalt tooth edge stands up to high temperatures, allowing faster cutting and reduced edge wear. The alloy back absorbs shock for a longer life. This combination results in a safer cutting tool that is virtually shatterproof.

#### Variable Tooth Pitch

We vary the size of the teeth and the depth of the gullets over the length of the blade. This variation brings teeth into the work at constantly changing angles, breaking up the harmonics encountered in sawing. This lets you cut faster and produce a smoother finish than you can with conventional blades. With less harmonic buildup you also cut quieter which lowers operator fatigue – a major cause of accidents. The varying gullets also give added protection against tooth stripping.


### Decreasing Blade Failure

#### Three significant ways to decrease blade failure

- Use a good quality cutting fluid
- Break in blade properly
- Run the machine at faster band speeds

### Applications

- Low speed – Stainless steel and other tough steels, electric cable and plastics
- High speed – Brass, aluminum, mild steel, angle iron, galvanized pipe, copper, bronze and magnesium



### Speed Chart

| Material                 | Type      | Speed (fpm)                       | Material                   | Type            | Speed (fpm)        | Material        | Type              | Speed (fpm)       | Material           | Type  | Speed (fpm) |
|--------------------------|-----------|-----------------------------------|----------------------------|-----------------|--------------------|-----------------|-------------------|-------------------|--------------------|-------|-------------|
| Carbon Steel             | 1008-1035 | 300                               | Chrome                     | 6117-6120       | 230                | Stainless Steel | 201, 202, 302     | 115               | Nickel Base Alloys | Monel | 100         |
|                          | 1040-1095 | 200                               |                            | Vanadium Steel  | 6145-6152          |                 | 200               | 304, 321, 347     |                    | 115   | 125-200 BHN |
| Free Machine Steels      | 1108-1132 | 340                               | Silicon Steel              | 9255-9260       | 190                | 303, 303F, 440F | 125               | R Monel           |                    | 140   |             |
|                          | 1212-1213 | 340                               |                            | 9261-9262       | 175                | 443             | 125               | 145-180 BHN       |                    | 140   |             |
| Manganese Steel          | 1137-1151 | 275                               | High-Speed Tool Steel      | T1, T2          | 130                | 308-310         | 80                | K Monel           |                    | 80    |             |
|                          | 1320-1345 | 220                               |                            | T4, T5, T6, T8  | 100                | 314-317, 330    | 80                | 100-210 BHN       |                    | 80    |             |
| Nickel Steel             | 2317      | 260                               |                            | T15             | 75                 | 410, 420, 420F  | 145               | K R Monel Inconel |                    | 95    |             |
|                          | 2330-2345 | 200                               |                            | M1              | 150                | 416, 430F       | 175               | Inconel X         |                    | 80    |             |
| Nickel Chrome Steel      | 2512-2517 | 190                               |                            | M2, M3          | 100                | 430, 446        | 90                | Hastelloy A       |                    | 110   |             |
|                          | 3115-3130 | 250                               |                            | M4, M10, M15    | 85                 | 440 A, B, C     | 105               | 210-260 BHN       |                    | 110   |             |
| Molybdenum Steel         | 3135-3150 | 250                               |                            | M42, M43        | 85                 | 17-4PH, 17-7PH  | 75                | Hastelloy B       | 100                |       |             |
|                          | 3310-3315 | 190                               | Die Steels                 | A2              | 190                | Aluminum Bronze | 400               | 230-270 BHN       | 100                |       |             |
| 4017-4042                | 270       | D2, D3                            |                            | 110             | Alum Bronze        | 170             | 185-250 BHN       | 90                |                    |       |             |
| 4047-4068                | 220       | D7                                |                            | 80              | 190-220 BHN        | 170             | Mst Gal-4V        | 100               |                    |       |             |
| Chrome Moly Steel        | 4130-4140 | 250                               | 01, 02, 06                 | 200             | Copper Base Alloys | Phosphur Bronze | 400               | 310-360 BHN       | 100                |       |             |
|                          | 4142-4150 | 210                               | Carbon Tool Steel          | W1              |                    | 220             | 5-8%, 60-100 BHN  | 400               | RC 130 B           | 100   |             |
| Nickel Chrome Moly Steel | 4317-4340 | 220                               | Hot Work Steel             | H-12, H-21      |                    | 180             | Phosphur Bronze   | 170               | 290-330 BHN        | 100   |             |
|                          | 4615-4645 | 220                               |                            | H-22, H-25      |                    | 160             | 5-8%, 180-210 BHN | 170               | Ti-140A            | 90    |             |
|                          | 8715-8750 | 220                               | Shock Resisting Tool Steel | S-1             |                    | 190             | Manganese Bronze  | 325               | 300-330 BHN        | 90    |             |
|                          | 9437-9445 | 230                               | S-2, S-5                   | 145             |                    | 90-120 BHN      | 325               | T 150A            | 90                 |       |             |
| Nickel Moly Steel        | 9747-9763 | 230                               | Special Purpose Tool Steel | L-6, L-7        |                    | 160             | Silicone Bronze   | 170               | 325-350 BHN        | 90    |             |
|                          | 9840-9850 | 230                               | Titanium Alloys            | Titanium Alloys |                    |                 | 70-100 BHN        | 170               | 99% Pure Titanium  | 90    |             |
| 4608-4640                | 220       | Silicone Bronze                   |                            |                 |                    |                 | 170               | 270-315 BHN       | 90                 |       |             |
| 4812-4820                | 190       | Beryllium Copper #25, 100-120 BHN |                            |                 |                    |                 | 275               |                   |                    |       |             |
| 5045-5046                | 250       | Beryllium Copper #25, 220-250 BHN |                            |                 | 225                |                 |                   |                   |                    |       |             |
| 5120-5135                | 250       | Beryllium Copper #25, 310-340 BHN |                            |                 | 140                |                 |                   |                   |                    |       |             |
| 5140-5160                | 230       |                                   |                            |                 |                    |                 |                   |                   |                    |       |             |
| 50100-52100              | 170       |                                   |                            |                 |                    |                 |                   |                   |                    |       |             |

### Wheel




#### How to use this chart:

1. Locate the length of cut in inches on the outside circle (for millimeters use the inside circle).
  - A. The length of the cut is the distance that any tooth of the blade is in contact with the work as it passes once through the cut.
  - B. For solid round stock, the diameter is the length of the cut
  - C. For angles, channels, I-beams, tubular pieces, pipe, and hollow or irregular shapes, the length of cut is found by dividing the cross-sectional area of the cut by the distance the blade needs to travel to finish the cut.
2. Find the tooth specification that aligns with the length, on the ring corresponding with the material shape.


### Tooth Selection

For best results, the correct number of teeth on the workpiece is of utmost importance. For mild materials, the 3–6–12–24 rule applies. For hard materials, the 6–12–24–48 rule applies.




### Vise Loading and Work-Holding Positions

Always tip angles so blade cuts largest cross section.




### Proper Clamping



## Break-In Procedures

Proper break-in of a saw blade is the single most important step in sawing. A saw blade that is not broken in will not last as long, cut as fast or as straight as one which has been properly broken in. The term break-in might be more correctly called tooth sharpening.

The process of break-in removes the dead sharp point and feather edge and places a fine radius on the tooth tip which allows the chip to shear away from the workpiece more readily and gives the required support to the tooth tip, which undergoes extreme forces in the cutting process.



### Recommended Method

1. Set band speed at normal fpm for material being cut.
2. Reduce feed force as low as possible while still pulling a chip.
3. Gradually increase feed force over 50-100 square inches until normal feed is reached.  
(50 square inches – difficult-to-cut material, 100 square inches – easy-to-cut material.)

If the material is difficult to cut, begin break-in with a heavier feed so the material does not work-harden and damage the tooth.

### Operational Cutting Note

Break-in is just as important for operational blades as it is for production blades. The key technique is No. 2 above. The material should be fed against the blade manually with just enough force to pull chips for the first couple of cuts. After that, a gradual build-up of force should do the trick.

## Causes of Failure

Band saw blades are subject to several types of stress. Operators can reduce blade changes by properly tensioning the blade, and adjusting and running the band saw machine to keep the blade within its designated stress limits.

### Some good rules that always apply:

- Maintain proper tightening stress of about 30,000 psi. That will make straight cutting easier.
- Keep guide arms as close together as possible. (For example, doubling the distance between them will double the bending stress on the blade.)
- Use only enough feed force to do the job consistent with other goals, such as cutting rate.
- Keep the machine in good condition and in proper adjustment.

### Over-tightening

- Higher tightening stress provides straighter cutting. A good rule of thumb for good blade life is to keep the stress less than 50% of the tensile strength of the blade's backing steel.
- Maximum stress occurs either at the front guide or where the band comes onto the drive wheel.
- By limiting the tightening stress to about 30,000 psi, ample margin remains to take care of these maximum stress points.

### Other Causes of Failure

- A fine tooth band will have a lower maximum stress than a coarse tooth band.
- Tensile strength can be altered significantly by damage to the band such as nicks or scratches, work-hardening or other conditions which introduce stress concentrating factors as large as 2 or 3.
- Normal fatigue failures begin at the gullet. Failures starting at the back edge or in the middle of the band indicate that some abnormal condition has influenced the failure.
- Minimize band breakage by selecting a wider band saw blade even if it is thicker. Using a thicker band will, however, reduce cutting rate. Increasing the feed force to maintain the cutting rate is self-defeating as far as breakage is concerned.