


Flanges up  
And against inside of leg

#1385675



Assemble base stand and place in location.  
Place 1385675 brackets inside each leg.  
(Bracket must be over bottom flange on leg.)  
Mark holes in brackets and remove.  
Drill for floor bolts as marked.  
(Removing base stand may help drilling.)  
Re-locate base stand, brackets and lag to floor.